



Ceramic 1500 Double Rectangle Bowl Vanity Top

9150EE-600

- **Finish:** Gloss White
- Vitreous China
- One Tap Hole or Three Tap Hole
- With Overflow
- Requires 32mm Waste with Overflow (not included)

Please note:

Standard manufacturing tolerances of Ceramic Basins & Tops are: +/- 0.5-2% . Standard Tap Hole variances on Ceramic Basins are 33-38mm Dia.

WARRANTY:

- 5 Year replacement product and parts
- 1 Year replacement parts and labour

It is highly recommended an application of sealant at the base of the mixer to ensure a water tight seal.